



Close up of a Leak control flange & acrylic flexible membrane on a shower drain



Fitting of a leak control flange



Leaking shower that has had the floor tiles and two rows of wall tiles removed. A Leak control flange has been fitted to the drain and the floor and wall have had Flexible waterproofing membrane applied.



New shower recess where a Leak control flange has been fitted to the floor waste pipe and the floor & wall junctions reinforced with reinforcing bandage and finished off with Flexible waterproofing membrane.